Test Report No. S08MEC04793/DL dated 22 Aug 2008



TEST RESULTS: (CONT'D)

PHOTOS TAKEN ON WINDOW #2 WITH ONE PAIR OF SAFETY DEVICES




Photo 3: Window #2 with one pair of safety devices – initial test setup

One pair of safety devices close-up view




Photo 4: After the fall, the sash remain intact on the outer frame for the next 24 hours.



Close-up view of safety devices after the fall

